FAASTeam presents:

An In-depth Study Into The Pinnacle Flight 3701 Accident

On October 14, 2004, Pinnacle Airlines flight 3701 crashed near Jefferson City, MO killing two crew members. The CRJ200 was on a reposition flight from Little Rock, Arkansas to Minneapolis, Minnesota and there was no flight attendant or passengers on board. The crew caused the accident chain of events, which lead to the crash. Most accounts of flight 3701 jump to the obvious unprofessionalism and poor airmanship of the crew, which was a major factor. However: there was more to the accident which lead to changes made industry wide with the CJR series aircraft. Mark Gaffney was flying for Pinnacle Airlines in 2004 when the accident occurred and can add a unique perspective on the accident. The presentation goes into detail on the chain of events, but also goes over CRJ systems and how they related to the accident. All major and regional airlines have incorporated the accident into their human factors training program. The presentation is a perfect fit for any flight student or CFI thinking about working for a regional airline. This is a private event for Ignite flight students and CFIs.

Directions: The private safety meeting will take place on the 2nd floor classroom at the Ignite Flight Academy located at the Lincoln Airport.

Event Details

Wed, Mar 22, 2023 - 17:30 CDT Ignite Flight Academy

1760 W Kearney Ave Lincoln, NE 68524



Contact: MARK MICHAEL GAFFNEY (402) 458-7812

mark.m.gaffney@faa.gov

Select #: CE09121120 FPM MARK MICHAEL GAFFNEY

A message from the National FAASTeam Manager

Earn your WINGS to get a chance to win a prize. Go to www.wingsindustry.net for more info.

Join us on Facebook: https://www.facebook.com/groups/GASafety/ Sign up for the FAA's safety services at www.FAASafety.gov!

The FAA Safety Team (FAASTeam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the "Contact Information" area of the meeting/event notice. Note that two weeks is usually required to arrange services.